ZKTeco

Installation Guide

FR1500S

Version: 1.0

Installation

Dimensions(mm)

77.3   38.0   7.1   121.3

Note: Not all the devices have the fingerprint cover. The real product prevails.

Procedure to be followed before installation

STEP 1 Remove both the screws

Method 1: Mounting on the standard Single gang junction box

Lay the cables from the desired hole in Single gang junction box and fix the machine part to the box part.

The Single gang junction box's size recommendations:
Location column: 83.3mm
Inside of the box Depth: Minimum 36mm
Outside the box size: maximum length 120mm , maximum width 76mm

Method 2: Mounting inside the wall

STEP 1
Place the mounting sticker to the place where device needs to be installed

STEP 2
Drill fixing holes and dig mounting groove deep of 36mm


wall

36mm

STEP 3
If cables need to be laid from behind then it must be done before installing

STEP 4
Install the device with the screws

STEP 5
After installing the back plate attach the machine part in the same reverse manner as shown in previous page