

11AC80MIMO_Ant1_5690_UNII-2C



11AC80MIMO_Ant0_5690_UNII-3



11AC80MIMO_Ant1_5690_UNII-3

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AC80MIMO_Ant0_5775



11AC80MIMO_Ant1_5775



11AX20MIMO_Ant0_5180

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_5180



11AX20MIMO_Ant0_5200



11AX20MIMO_Ant1_5200

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5240



11AX20MIMO_Ant1_5240



11AX20MIMO_Ant0_5260

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_5260



11AX20MIMO_Ant0_5280



11AX20MIMO_Ant1_5280

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5320



11AX20MIMO_Ant1_5320



11AX20MIMO_Ant0_5500

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_5500



11AX20MIMO_Ant0_5580



11AX20MIMO_Ant1_5580

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5700



11AX20MIMO_Ant1_5700

11AX20MIMO_Ant0_5720_UNII-2C

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_5720_UNII-2C



11AX20MIMO_Ant0_5720_UNII-3

11AX20MIMO_Ant1_5720_UNII-3

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant0_5745



11AX20MIMO_Ant1_5745



11AX20MIMO_Ant0_5785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_5785



11AX20MIMO_Ant0_5825



11AX20MIMO_Ant1_5825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_5190



11AX40MIMO_Ant1_5190



11AX40MIMO_Ant0_5230

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_5230



11AX40MIMO_Ant0_5270



11AX40MIMO_Ant1_5270

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_5310



11AX40MIMO_Ant1_5310



11AX40MIMO_Ant0_5510

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_5510



11AX40MIMO_Ant0_5550



11AX40MIMO_Ant1_5550

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_5670



11AX40MIMO_Ant1_5670



11AX40MIMO_Ant0_5710_UNII-2C

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_5710_UNII-2C



11AX40MIMO_Ant0_5710_UNII-3



11AX40MIMO_Ant1_5710_UNII-3

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant0_5755



11AX40MIMO_Ant1_5755



11AX40MIMO_Ant0_5795

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_5795



11AX80MIMO_Ant0_5210



11AX80MIMO_Ant1_5210

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant0_5290



11AX80MIMO_Ant1_5290



11AX80MIMO_Ant0_5530

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_5530



11AX80MIMO_Ant0_5610



11AX80MIMO_Ant1_5610

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant0_5690_UNII-2C



11AX80MIMO_Ant1_5690_UNII-2C



11AX80MIMO_Ant0_5690_UNII-3

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.