











Remark: Fuse should be solder on negative battery teminal





2408-2460MHz