


















11.6. Appendix F: Conducted Spurious Emission 11.6.1. Test Result

Test Mode	Antenna	Channel	Freq Range	Result	Limit	Verdict
1 CSt WOOC	Antonia	Onamici	[Mhz]	[dBm]	[dBm]	
			Reference	2.10		PASS
	Ant1	2412	30~1000	-52.21	<=-27.9	PASS
			1000~26500	-40.35	<=-27.9	PASS
			Reference	1.01		PASS
	Ant2	2412	30~1000	-52.07	<=-28.99	PASS
			1000~26500	-43.59	<=-28.99	PASS
	Ant1	2437	Reference	1.50		PASS
			30~1000	-52.94	<=-28.5	PASS
11B-CDD			1000~26500	-42.02	<=-28.5	PASS
	Ant2	2437	Reference	0.28		PASS
			30~1000	-52.86	<=-29.72	PASS
			1000~26500	-43.64	<=-29.72	PASS
	Ant1	2462	Reference	1.68		PASS
			30~1000	-52.68	<=-28.32	PASS
			1000~26500	-43.21	<=-28.32	PASS
			Reference	0.24		PASS
	Ant2	2462	30~1000	-52.91	<=-29.76	PASS
			1000~26500	-43.95	<=-29.76	PASS
			Reference	2.71		PASS
	Ant1	2412	30~1000	-51.84	<=-27.29	PASS
			1000~26500	-43.44	<=-27.29	PASS
		2412	Reference	-0.31		PASS
	Ant2		30~1000	-52.45	<=-30.31	PASS
			1000~26500	-43.73	<=-30.31	PASS
	Ant1	2437	Reference	3.03		PASS
11G-CDD			30~1000	-52.06	<=-26.97	PASS
			1000~26500	-43.37	<=-26.97	PASS
TIG-CDD	Ant2	2437	Reference	2.37		PASS
			30~1000	-52.48	<=-27.63	PASS
			1000~26500	-43.47	<=-27.63	PASS
	Ant1	2462	Reference	2.16		PASS
			30~1000	-52.86	<=-27.84	PASS
			1000~26500	-44.05	<=-27.84	PASS
	Ant2	2462	Reference	1.74		PASS
			30~1000	-52.83	<=-28.26	PASS
			1000~26500	-43.59	<=-28.26	PASS
	Ant1	2412	Reference	1.54		PASS
			30~1000	-52.73	<=-28.46	PASS
			1000~26500	-43.46	<=-28.46	PASS
	Ant2	2412	Reference	1.72		PASS
			30~1000	-52.76	<=-28.28	PASS
			1000~26500	-43.51	<=-28.28	PASS
	Ant1	2437	Reference	2.70		PASS
			30~1000	-52.13	<=-27.3	PASS
11N20MIMO			1000~26500	-43.84	<=-27.3	PASS
	Ant2	2437	Reference	0.88		PASS
			30~1000	-53.16	<=-29.12	PASS
			1000~26500	-43.53	<=-29.12	PASS
	Ant1	2462	Reference	2.42		PASS
			30~1000	-52.66	<=-27.58	PASS
			1000~26500	-44.12	<=-27.58	PASS
	Ant2	2462	Reference	2.12		PASS
			30~1000	-52.42	<=-27.88	PASS





			1000~26500	-43.99	<=-27.88	PASS
11N40MIMO	Ant1	2422	Reference	0.24		PASS
			30~1000	-52.04	<=-29.76	PASS
			1000~26500	-44.52	<=-29.76	PASS
	Ant2	2422	Reference	-2.30		PASS
			30~1000	-52.05	<=-32.3	PASS
			1000~26500	-43.56	<=-32.3	PASS
	Ant1	2437	Reference	-1.44		PASS
			30~1000	-52.71	<=-31.44	PASS
			1000~26500	-44.17	<=-31.44	PASS
	Ant2	2437	Reference	-2.61		PASS
			30~1000	-52.69	<=-32.61	PASS
			1000~26500	-43.59	<=-32.61	PASS
	Ant1	2452	Reference	-1.60		PASS
			30~1000	-52.75	<=-31.6	PASS
			1000~26500	-42.85	<=-31.6	PASS
	Ant2	2452	Reference	-1.96		PASS
			30~1000	-52.36	<=-31.96	PASS
			1000~26500	-43.64	<=-31.96	PASS



11.6.2. Test Graphs

