

10. SETUP PHOTOS


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)



Page 53 of 57




RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)






POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB LAPTOP



Page 55 of 57



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER



Page 56 of 57



END OF REPORT