



Communication Components, Inc.

89 Leuning Street

South Hackensack, NJ 07606

Phone: 201-342-3338

Fax: 201-342-3339

SCB-850-1W-ALU-OD-1 Tune up Procedure

There is no tune up procedure for the CCI# SCB-850-1W-ALU-OD-1. It is simply a single input, single output, single channel full duplex amplifier with a second Rx diversity / Tx bypass channel. Any gain adjustments must be performed by utilizing an external attenuator.

All necessary repairs and adjustments are performed at the factory by trained personnel.

Dated this 07th **Day** May **20** **14**
of _____

By:



Dennis Nathan

Signature

Printed

Title: President

On behalf of: Communication Components Inc.