

Response for JVP56D98

1. Will be uploaded
2. The new technical spec keeps the same spec, but adding the factory tune-up target (in red color word)
3. updated
4. updated
5. will be uploaded as a separate file
6. confirmed
7. Yes, GPRS and voice can not transmit simultaneously
8. Actually, the area scan is large enough and the hot spot is included. The view is top view and the vertical part of the scan area on the cheek was not easily to identify. I will send you the plottings with different view angle.
9. The same with item 8