



5MHz_Low_QPSK_1@0 -24.53dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:18:06

5MHz_Low_QPSK_25@0 -24.27dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:05:36

5MHz_Middle_QPSK_1@0 -24.30dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:19:05

5MHz_Middle_QPSK_25@0 -23.01dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:19:32

5MHz_High_QPSK_1@0 -24.08dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:20:08

5MHz_High_QPSK_25@0 -24.26dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:05:54

10MHz_Low_QPSK_1@0 -24.80dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:21:13

10MHz_Low_QPSK_50@0 -24.20dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:21:42

10MHz_Middle_QPSK_1@0 -24.59dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:22:13

10MHz_Middle_QPSK_50@0 -23.98dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:22:44

10MHz_High_QPSK_1@0 -24.63dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:29:37

10MHz_High_QPSK_50@0 -24.10dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:30:07

15MHz_Low_QPSK_1@0 -23.59dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:30:42

15MHz_Low_QPSK_75@0 -23.46dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:31:13

15MHz_Middle_QPSK_1@0 -24.73dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:31:46

15MHz_Middle_QPSK_75@0 -24.76dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:32:17

15MHz_High_QPSK_1@0 -24.80dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:34:19

15MHz_High_QPSK_75@0 -24.42dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:34:49

20MHz_Low_QPSK_1@0 -24.35dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:35:24

20MHz_Low_QPSK_100@0 -24.63dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:35:54

20MHz_Middle_QPSK_1@0 -24.15dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:36:26

20MHz_Middle_QPSK_100@0 -24.76dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:36:56

20MHz_High_QPSK_1@0 -24.93dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:37:30


20MHz_High_QPSK_100@0 -24.44dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:38:00


B7, Normal

5MHz_Low_QPSK_1@0 -34.36dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:53:44

5MHz_Low_QPSK_25@0 -34.68dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:54:17

5MHz_Middle_QPSK_1@0 -33.92dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:54:52

5MHz_Middle_QPSK_25@0 -34.68dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:55:25

5MHz_High_QPSK_1@0 -34.09dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:55:59

5MHz_High_QPSK_25@0 -34.40dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:56:32

10MHz_Low_QPSK_1@0 -34.62dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:57:12

10MHz_Low_QPSK_50@0 -34.30dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:57:44

10MHz_Middle_QPSK_1@0 -34.83dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:58:18

10MHz_Middle_QPSK_50@0 -34.14dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:58:51

10MHz_High_QPSK_1@0 -34.97dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:59:26

10MHz_High_QPSK_50@0 -34.54dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:00:01

15MHz_Low_QPSK_1@0 -34.21dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:00:41

15MHz_Low_QPSK_75@0 -34.30dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:01:16

15MHz_Middle_QPSK_1@0 -34.74dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:01:50

15MHz_Middle_QPSK_75@0 -35.04dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:02:22

15MHz_High_QPSK_1@0 -36.69dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:02:57

15MHz_High_QPSK_75@0 -34.51dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:03:30

20MHz_Low_QPSK_1@0 -34.85dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:04:07

20MHz_Low_QPSK_100@0 -34.78dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:06:20

20MHz_Middle_QPSK_1@0 -35.15dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:05:14

20MHz_Middle_QPSK_100@0 -35.02dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:05:47

20MHz_High_QPSK_1@0 -34.41dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:06:22


20MHz_High_QPSK_100@0 -34.96dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:06:55


B12 , Normal

1.4MHz_Low_QPSK_1@0 -25.63dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:07:32

1.4MHz_Low_QPSK_6@0 -25.49dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:08:02

1.4MHz_Middle_QPSK_1@0 -25.76dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:08:31

1.4MHz_Middle_QPSK_6@0 -25.38dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:08:59

1.4MHz_High_QPSK_1@0 -25.19dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:09:29

1.4MHz_High_QPSK_6@0 -25.94dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:10:00

3MHz_Low_QPSK_1@0 -25.79dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:10:33

3MHz_Low_QPSK_15@0 -24.77dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:11:02

3MHz_Middle_QPSK_1@0 -25.33dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:11:33

3MHz_Middle_QPSK_15@0 -25.81dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:12:03

3MHz_High_QPSK_1@0 -25.74dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:12:33

3MHz_High_QPSK_15@0 -25.76dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:13:01

5MHz_Low_QPSK_1@0 -24.93dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:13:35

5MHz_Low_QPSK_25@0 -25.75dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:14:07

5MHz_Middle_QPSK_1@0 -24.85dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:14:39

5MHz_Middle_QPSK_25@0 -25.18dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:15:11

5MHz_High_QPSK_1@0 -25.60dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:15:43

5MHz_High_QPSK_25@0 -26.02dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:16:15

10MHz_Low_QPSK_1@0 -25.41dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:16:51

10MHz_Low_QPSK_50@0 -25.53dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:17:23

10MHz_Middle_QPSK_1@0 -25.53dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:17:56

10MHz_Middle_QPSK_50@0 -24.95dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:18:28

10MHz_High_QPSK_1@0 -24.95dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:18:58


10MHz_High_QPSK_50@0 -25.64dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:19:31


B13 , Normal

5MHz_Low_QPSK_1@0 -25.99dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:20:07

5MHz_Low_QPSK_25@0 -26.01dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:21:46

5MHz_High_QPSK_1@0 -25.61dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:31:48

5MHz_High_QPSK_25@0 -25.78dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:34:34

10MHz_Middle_QPSK_1@0 -25.19dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:36:19


10MHz_Middle_QPSK_50@0 -26.15dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:36:46


B17 , Normal

5MHz_Low_QPSK_1@0 -25.51dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:39:36

5MHz_Low_QPSK_25@0 -26.35dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:40:02

5MHz_Middle_QPSK_1@0 -25.27dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:40:28

5MHz_Middle_QPSK_25@0 -25.63dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:40:53

5MHz_High_QPSK_1@0 -25.31dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:41:19

5MHz_High_QPSK_25@0 -25.81dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:41:44

10MHz_Low_QPSK_1@0 -25.93dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:42:14

10MHz_Low_QPSK_50@0 -25.63dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:42:19

10MHz_Middle_QPSK_1@0 -25.15dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:43:07

10MHz_Middle_QPSK_50@0 -25.68dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:43:32

10MHz_High_QPSK_1@0 -24.71dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:43:58


10MHz_High_QPSK_50@0 -25.98dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:44:24


B38 , Normal

5MHz_Low_QPSK_1@0 -33.88dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:53:25

5MHz_Low_QPSK_25@0 -34.76dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:53:56

5MHz_Middle_QPSK_1@0 -34.45dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:54:29

5MHz_Middle_QPSK_25@0 -35.05dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:55:00

5MHz_High_QPSK_1@0 -35.13dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:55:33

5MHz_High_QPSK_25@0 -34.97dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:56:04

10MHz_Low_QPSK_1@0 -34.75dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:56:37

10MHz_Low_QPSK_50@0 -34.65dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:57:07

10MHz_Middle_QPSK_1@0 -34.41dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:57:38

10MHz_Middle_QPSK_50@0 -35.19dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:58:09

10MHz_High_QPSK_1@0 -34.77dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:58:39

10MHz_High_QPSK_50@0 -35.07dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:59:11

15MHz_Low_QPSK_1@0 -34.19dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:59:43

15MHz_Low_QPSK_75@0 -34.40dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:00:15

15MHz_Middle_QPSK_1@0 -34.68dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:00:48

15MHz_Middle_QPSK_75@0 -33.97dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:01:20

15MHz_High_QPSK_1@0 -34.30dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:01:50

15MHz_High_QPSK_75@0 -34.38dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:02:21

20MHz_Low_QPSK_1@0 -32.49dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:02:58

20MHz_Low_QPSK_100@0 -34.54dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:03:31

20MHz_Middle_QPSK_1@0 -34.45dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:04:05

20MHz_Middle_QPSK_100@0 -34.12dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:31:12

20MHz_High_QPSK_1@0 -33.58dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:05:10


20MHz_High_QPSK_100@0 -34.56dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:05:43


B66 , Normal

1.4MHz_Low_QPSK_1@0 -24.31dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:22:23

1.4MHz_Low_QPSK_6@0 -24.37dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:22:52

1.4MHz_Middle_QPSK_1@0 -24.40dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:23:24

1.4MHz_Middle_QPSK_6@0 -25.04dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:23:55

1.4MHz_High_QPSK_1@0 -24.72dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:24:28

1.4MHz_High_QPSK_6@0 -24.55dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:24:58

3MHz_Low_QPSK_1@0 -23.93dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:25:33

3MHz_Low_QPSK_15@0 -24.57dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:26:02

3MHz_Middle_QPSK_1@0 -24.37dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:26:35

3MHz_Middle_QPSK_15@0 -25.07dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:27:06

3MHz_High_QPSK_1@0 -23.45dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:27:39

3MHz_High_QPSK_15@0 -24.57dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:28:11