

Thundercomm Technology Co., Ltd
Address: Building 4, No. 99, Data Valley Middle Road, Xiantao District, Yubei District,
Chongqing, China
Tel.: +86 010-82036511 Fax: +86 010-82036511
E-mail: Zhouqy0710@thundersoft.com

FEDERAL COMMUNICATIONS COMMISSION
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Subject: Request to change in Identification.

Date: 2021-10-13

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID: 2AOHHTURBOXC5165DK as established in 47CFR2.933(b) for a currently approved device. This application by Thundercomm Technology Co., Ltd will establish a new FCC ID: 2AOHHTURBOXC5165DK under Thundercomm Technology Co., Ltd grant code for purpose of marketing, and the new model will be under new FCC ID. The original grant to Thundercomm Technology Co., Ltd (FCC ID: 2AOHH-TURBOXC865) will remain in effect.

Per 2.933(b)

1. The original identification is Thundercomm Technology Co., Ltd (FCC ID: 2AOHH-TURBOXC865)
2. The Original grant date is 09/15/2021
3. The equipment is electrically identical, only the FCC ID number, Product name, model and label are different. The details are as follows:
 - (1) Changing the FCC ID number to "FCC ID: 2AOHHTURBOXC5165DK".
 - (2) Changing the product name to "Robotics 5165".
 - (3) Changing the model name to "Robotics RB5 Core Kit".
4. The original test results are applicable and representative of this changed device
5. Exterior photographs are included in this application

The following files are electronically submit as attachments:

Cover letter

External photos

FCC ID Label format and location

Sincerely,

Qiyong Zhou

Qiyong Zhou

Manager