In Page 1 of 2

To: "Timothy R. Johnson" <tjohnson@AmericanTCB.com> Subject: Re: FCC ID: MQ4WB1K5S

Dear Timothy,

As per your review comments for FCC ID: MQ4WB1K5S, please see the explanation as below:

- Please find the revised diagram attached which provided by our client as per your requirement.
- 2) Please find the revised manual and revised label attached for your review.
- 3) Please also find the revised manual attached for your reference.
- 4) We modified the report regarding to your requirement. Please find the revised report attached.
- 5) For the statement for RBW and VBW setting, please refer to the section 2.1 of report.

I hope the supplements satisfy all your requirement for reviewing this application. If you have further question, please feel free to contact me.

Thank you very much for your kindly help on this project.

Best Regards, Julia Chu

---- Original Message -----

From: "Timothy R. Johnson" <tjohnson@AmericanTCB.com>

To: <jchu@itslabtest-twn.com>
Cc: <MCHEN@itslabtest-twn.com>

Sent: Wednesday, October 02, 2002 12:25 PM

Subject: Preliminary Review of AboCom System, Inc., FCC ID: MQ4WB1K5S

Michael,

Attached are comments regarding review of this application.

Thank You,

Timothy R. Johnson, NARTE Certified EMC Engineer (No. EMC-002205-NE) Examining Engineer

In Page 2 of 2

American TCB, Inc. 6731 Whittier Ave. McLean, VA 22101

email: tjohnson@AmericanTCB.com

alternate email: TRJ@adelphia.net

direct number: 404-414-8071 corporate phone: 703-847-4700 corporate fax: 703-847-6888



revised-report.pdf



revised-Installation guide.pdf



revised-label.pdf



revise-block diagram.pdf