



2_20MHz_High_16QAM_1@99



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 5.JUL.2024 14:48:18

2_20MHz_High_16QAM_100@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 5.JUL.2024 14:48:06

Spurious Emissions at Antenna Terminal

FCC For 90S


B26_1, Normal

1_1.4MHz_Low_QPSK_1@0 -25.46dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:06:52

1_1.4MHz_Low_QPSK_6@0 -26.11dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:07:08

1_1.4MHz_High_QPSK_1@0 -25.79dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:07:56

1_1.4MHz_High_QPSK_6@0 -25.36dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:08:12

1_3MHz_Low_QPSK_1@0 -25.60dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:08:31

1_3MHz_Low_QPSK_15@0 -25.90dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:08:47

1_3MHz_High_QPSK_1@0 -25.02dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:09:35

1_3MHz_High_QPSK_15@0 -25.69dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:09:52

1_5MHz_Low_QPSK_1@0 -25.78dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:11:47

1_5MHz_Low_QPSK_25@0 -25.54dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:12:03

1_5MHz_High_QPSK_1@0 -25.72dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:12:49

1_5MHz_High_QPSK_25@0 -25.49dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:13:03

1_10MHz_Middle_QPSK_1@0 -25.97dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:13:27

1_10MHz_Middle_QPSK_50@0 -26.13dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:13:41

1_15MHz_Low_QPSK_1@0 -25.07dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:13:59


1_15MHz_Low_QPSK_75@0 -25.71dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:14:13


B26_3, Normal

3_1.4MHz_Middle_QPSK_1@0 -24.83dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 1.JUL.2024 11:39:35


3_1.4MHz_Middle_QPSK_6@0 -25.72dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 1.JUL.2024 11:39:50


26_3, Normal

3_3MHz_Middle_QPSK_1@0 -25.88dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 1.JUL.2024 11:40:08

3_3MHz_Middle_QPSK_15@0 -25.72dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 1.JUL.2024 11:40:24

3_5MHz_Middle_QPSK_1@0 -25.52dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 1.JUL.2024 11:40:42

3_5MHz_Middle_QPSK_25@0 -25.64dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 1.JUL.2024 11:40:58

3_10MHz_Middle_QPSK_1@0 -25.64dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 1.JUL.2024 11:41:16

3_10MHz_Middle_QPSK_50@0 -26.02dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 1.JUL.2024 11:41:31

3_15MHz_Middle_QPSK_1@0 -25.88dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 1.JUL.2024 11:41:56

3_15MHz_Middle_QPSK_75@0 -25.84dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 1.JUL.2024 11:42:11


FCC Part 22H

B5, Normal


1.4MHz_Low_QPSK_1@0 -25.22dBm




1.4MHz_Low_QPSK_6@0 -25.84dBm




1.4MHz_Middle_QPSK_1@0 -25.82dBm




1.4MHz_Middle_QPSK_6@0 -25.96dBm




1.4MHz_High_QPSK_1@0 -25.43dBm



1.4MHz_High_QPSK_6@0 -25.62dBm




3MHz_Low_QPSK_1@0 -25.79dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:41:30

3MHz_Low_QPSK_15@0 -25.16dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:41:57

3MHz_Middle_QPSK_1@0 -25.12dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:42:26

3MHz_Middle_QPSK_15@0 -26.46dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:30:22

3MHz_High_QPSK_1@0 -25.00dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:44:17

3MHz_High_QPSK_15@0 -25.18dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:44:45

5MHz_Low_QPSK_1@0 -25.23dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:45:42

5MHz_Low_QPSK_25@0 -25.50dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:46:12

5MHz_Middle_QPSK_1@0 -25.09dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:46:42

5MHz_Middle_QPSK_25@0 -25.08dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:47:11

5MHz_High_QPSK_1@0 -25.72dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:47:40

5MHz_High_QPSK_25@0 -27.90dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:49:01

10MHz_Low_QPSK_1@0 -25.33dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:49:32

10MHz_Low_QPSK_50@0 -25.87dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:49:59

10MHz_Middle_QPSK_1@0 -25.81dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:50:50

10MHz_Middle_QPSK_50@0 -25.49dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:51:17

10MHz_High_QPSK_1@0 -25.95dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:52:40


10MHz_High_QPSK_50@0 -25.99dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:53:07


B26_2, Normal

2_1.4MHz_Low_QPSK_1@0 -25.89dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:44:57

2_1.4MHz_Low_QPSK_6@0 -25.75dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:45:24

2_1.4MHz_Middle_QPSK_1@0 -25.79dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:45:51

2_1.4MHz_Middle_QPSK_6@0 -25.17dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:46:18

2_1.4MHz_High_QPSK_1@0 -25.30dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:46:46

2_1.4MHz_High_QPSK_6@0 -25.65dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:47:13

2_3MHz_Low_QPSK_1@0 -25.64dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:47:45

2_3MHz_Low_QPSK_15@0 -25.77dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:48:12

2_3MHz_Middle_QPSK_1@0 -25.41dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:48:38

2_3MHz_Middle_QPSK_15@0 -25.80dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 10:49:04

2_3MHz_High_QPSK_1@0 -26.32dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:14:31

2_3MHz_High_QPSK_15@0 -25.06dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:14:46

2_5MHz_Low_QPSK_1@0 -24.54dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:15:03

2_5MHz_Low_QPSK_25@0 -25.87dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:15:18

2_5MHz_Middle_QPSK_1@0 -25.08dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:17:22

2_5MHz_Middle_QPSK_25@0 -25.16dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:17:37

2_5MHz_High_QPSK_1@0 -25.56dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:17:52

2_5MHz_High_QPSK_25@0 -25.56dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:18:08

2_10MHz_Low_QPSK_1@0 -25.84dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:18:26

2_10MHz_Low_QPSK_50@0 -25.33dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:18:42

2_10MHz_Middle_QPSK_1@0 -25.68dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:18:57

2_10MHz_Middle_QPSK_50@0 -25.67dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:19:12

2_10MHz_High_QPSK_1@0 -26.00dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:19:28

2_10MHz_High_QPSK_50@0 -25.81dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:19:44

2_15MHz_Low_QPSK_1@0 -25.56dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:20:04

2_15MHz_Low_QPSK_75@0 -25.66dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:20:20

2_15MHz_Middle_QPSK_1@0 -25.90dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:20:37

2_15MHz_Middle_QPSK_75@0 -24.91dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:20:53

2_15MHz_High_QPSK_1@0 -25.80dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:21:09

2_15MHz_High_QPSK_75@0 -25.95dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:21:25


FCC Part 24E

B2 , Normal


1.4MHz_Low_QPSK_1@0 -24.79dBm




1.4MHz_Low_QPSK_6@0 -24.02dBm




1.4MHz_Middle_QPSK_1@0 -24.08dBm




1.4MHz_Middle_QPSK_6@0 -24.60dBm




1.4MHz_High_QPSK_1@0 -23.60dBm



1.4MHz_High_QPSK_6@0 -23.67dBm




3MHz_Low_QPSK_1@0 -21.82dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 08:56:49

3MHz_Low_QPSK_15@0 -23.12dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 08:57:19

3MHz_Middle_QPSK_1@0 -20.77dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 08:57:50

3MHz_Middle_QPSK_15@0 -23.87dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 08:58:21

3MHz_High_QPSK_1@0 -20.93dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 08:58:53

3MHz_High_QPSK_15@0 -24.45dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 08:59:25

5MHz_Low_QPSK_1@0 -20.73dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 08:59:59

5MHz_Low_QPSK_25@0 -24.24dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:00:28

5MHz_Middle_QPSK_1@0 -22.11dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:00:59

5MHz_Middle_QPSK_25@0 -24.34dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:01:28

5MHz_High_QPSK_1@0 -20.77dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:01:59

5MHz_High_QPSK_25@0 -24.92dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:02:28

10MHz_Low_QPSK_1@0 -22.62dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:02:59

10MHz_Low_QPSK_50@0 -24.23dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:03:28

10MHz_Middle_QPSK_1@0 -19.46dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:03:58

10MHz_Middle_QPSK_50@0 -24.69dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:04:27

10MHz_High_QPSK_1@0 -21.58dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:04:55

10MHz_High_QPSK_50@0 -24.22dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:05:25

15MHz_Low_QPSK_1@0 -19.46dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:05:58

15MHz_Low_QPSK_75@0 -24.22dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:06:28

15MHz_Middle_QPSK_1@0 -22.31dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:06:58

15MHz_Middle_QPSK_75@0 -24.85dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:07:27

15MHz_High_QPSK_1@0 -21.64dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:07:57

15MHz_High_QPSK_75@0 -23.23dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:08:27

20MHz_Low_QPSK_1@0 -22.10dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:09:02

20MHz_Low_QPSK_100@0 -23.39dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:09:32

20MHz_Middle_QPSK_1@0 -19.75dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:10:03

20MHz_Middle_QPSK_100@0 -24.55dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:10:32

20MHz_High_QPSK_1@0 -22.99dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:11:03

20MHz_High_QPSK_100@0 -24.15dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:11:32

FCC Part 27


B4, Normal

1.4MHz_Low_QPSK_1@0 -25.03dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 15:05:16

1.4MHz_Low_QPSK_6@0 -24.06dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:12:36

1.4MHz_Middle_QPSK_1@0 -24.50dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:13:03

1.4MHz_Middle_QPSK_6@0 -24.46dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:13:32

1.4MHz_High_QPSK_1@0 -23.86dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:14:00

1.4MHz_High_QPSK_6@0 -25.08dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:14:30

3MHz_Low_QPSK_1@0 -24.15dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:15:04

3MHz_Low_QPSK_15@0 -24.29dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:15:34

3MHz_Middle_QPSK_1@0 -24.35dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:16:05

3MHz_Middle_QPSK_15@0 -23.84dBm




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:16:34

3MHz_High_QPSK_1@0 -24.53dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:17:05

3MHz_High_QPSK_15@0 -24.17dBm



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 09:17:34