



## 11.6. APPENDIX F: INBAND EMISSIONS 11.6.1. Test Result-6ID

Test Mode	Antenna	Frequency [MHz]	Result	Limit	Verdict
	AntO	5975	See test graph	See test graph	PASS
		6135	See test graph	See test graph	PASS
		6375	See test graph	See test graph	PASS
		6455	See test graph	See test graph	PASS
11A		6535	See test graph	See test graph	PASS
		6695	See test graph	See test graph	PASS
		6855	See test graph	See test graph	PASS
		6935	See test graph	See test graph	PASS
		7015	See test graph	See test graph	PASS
		7095	See test graph	See test graph	PASS
	AntO	5955	See test graph	See test graph	PASS
		6175	See test graph	See test graph	PASS
		6415	See test graph	See test graph	PASS
		6435	See test graph	See test graph	PASS
		6475	See test graph	See test graph	PASS
114.200		6515	See test graph	See test graph	PASS
11AX20		6535	See test graph	See test graph	PASS
		6715	See test graph	See test graph	PASS
		6855	See test graph	See test graph	PASS
		6875	See test graph	See test graph	PASS
		7015	See test graph	See test graph	PASS
		7115	See test graph	See test graph	PASS
11AX40	Ant0	5965	See test graph	See test graph	PASS

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

## REPORT NO.: 4791508375-RF-4 Page 810 of 961



		6165	See test graph	See test graph	PASS
		6405	See test graph	See test graph	PASS
		6445	See test graph	See test graph	PASS
		6485	See test graph	See test graph	PASS
		6525	See test graph	See test graph	PASS
		6565	See test graph	See test graph	PASS
		6685	See test graph	See test graph	PASS
		6845	See test graph	See test graph	PASS
		6885	See test graph	See test graph	PASS
		7005	See test graph	See test graph	PASS
		7085	See test graph	See test graph	PASS
	AntO	5985	See test graph	See test graph	PASS
		6145	See test graph	See test graph	PASS
		6385	See test graph	See test graph	PASS
		6465	See test graph	See test graph	PASS
11AX80		6545	See test graph	See test graph	PASS
11AX80		6705	See test graph	See test graph	PASS
		6785	See test graph	See test graph	PASS
		6865	See test graph	See test graph	PASS
		6945	See test graph	See test graph	PASS
		7025	See test graph	See test graph	PASS
	Ant0	6025	See test graph	See test graph	PASS
		6185	See test graph	See test graph	PASS
11AX160		6345	See test graph	See test graph	PASS
1147100		6505	See test graph	See test graph	PASS
		6665	See test graph	See test graph	PASS
		6825	See test graph	See test graph	PASS

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

## REPORT NO.: 4791508375-RF-4 Page 811 of 961



					<b>-</b> •
		6985	See test graph	See test graph	PASS
	AntO	5955	See test graph	See test graph	PASS
		6175	See test graph	See test graph	PASS
		6415	See test graph	See test graph	PASS
		6435	See test graph	See test graph	PASS
		6475	See test graph	See test graph	PASS
11BE20		6515	See test graph	See test graph	PASS
TIBEZO		6535	See test graph	See test graph	PASS
		6715	See test graph	See test graph	PASS
		6855	See test graph	See test graph	PASS
		6875	See test graph	See test graph	PASS
		7015	See test graph	See test graph	PASS
		7115	See test graph	See test graph	PASS
	AntO	5965	See test graph	See test graph	PASS
		6165	See test graph	See test graph	PASS
		6405	See test graph	See test graph	PASS
		6445	See test graph	See test graph	PASS
		6485	See test graph	See test graph	PASS
		6525	See test graph	See test graph	PASS
11BE40		6565	See test graph	See test graph	PASS
		6725	See test graph	See test graph	PASS
		6845	See test graph	See test graph	PASS
		6885	See test graph	See test graph	PASS
		7005	See test graph	See test graph	PASS
		7085	See test graph	See test graph	PASS
11BE80	Ant0	5985	See test graph	See test graph	PASS
		6145	See test graph	See test graph	PASS

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.




		6385	See test graph	See test graph	PASS
		6465	See test graph	See test graph	PASS
		6545	See test graph	See test graph	PASS
		6705	See test graph	See test graph	PASS
		6785	See test graph	See test graph	PASS
		6865	See test graph	See test graph	PASS
		6945	See test graph	See test graph	PASS
		7025	See test graph	See test graph	PASS
11BE160	Ant0	6025	See test graph	See test graph	PASS
		6185	See test graph	See test graph	PASS
		6345	See test graph	See test graph	PASS
		6505	See test graph	See test graph	PASS
		6665	See test graph	See test graph	PASS
		6825	See test graph	See test graph	PASS
		6985	See test graph	See test graph	PASS

Note: All the modes and antennas had been tested, but only the worst data were recorded in the report.



## 11.6.2. Test Graphs-6ID



UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch FORM NO: 10-SL-F0035 This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.