



Intertek Testing Services

ETL SEMKO

Report No.: 03084241
Talk (4 Handsets) Mode

Tested By: Hong, Report No.: 03084241

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB


Final Measurement: x QP / + AV

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 03084241
Talk (4 Handsets) Mode

Tested By: Hong, Report No.: 03084241

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

Frequency QP Level QP Limit

MHz dBuV dBuV

0.37000 33.2 58.5

0.47500 33.6 56.4

0.71500 27.1 56.0

Frequency AV Level AV Limit

MHz dBuV dBuV

no Results

* limit



Intertek Testing Services

ETL SEMKO

Report No.: 03084242
Charging Mode with
Additional Charger

Tested By: Hong, Report No.: 03084242

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 03084242
Charging Mode with
Additional Charger

Tested By: Hong, Report No.: 03084242

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

no Results

Ctrl No.: N/A