



10MHz_High_QPSK_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:21:37

10MHz_High_QPSK_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:22:32

10MHz_High_16QAM_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:23:26

10MHz_High_16QAM_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:24:20

15MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:25:34

15MHz_Low_QPSK_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:26:39

15MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:27:45

15MHz_Low_16QAM_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:28:51

15MHz_High_QPSK_1@74




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:34:28

15MHz_High_QPSK_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:35:34

15MHz_High_16QAM_1@74




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:36:40

15MHz_High_16QAM_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:37:46

20MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:39:49

20MHz_Low_QPSK_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:41:05

20MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:42:120

20MHz_Low_16QAM_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:43:36

20MHz_High_QPSK_1@99




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:49:44

20MHz_High_QPSK_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:51:00

20MHz_High_16QAM_1@99



20MHz_High_16QAM_100@0




Spurious Emissions at Antenna Terminal


FCC Part 22H&IC RSS 132

B5, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



3MHz_High_QPSK_1@0(30MHz~9.49GHz)




5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:26:13

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:26:30

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:26:46

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:27:07

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:27:24

10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:27:40


FCC Part 24E&IC RSS 133

B2, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



3MHz_High_QPSK_1@0(30MHz~20.1GHz)




5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:07:09

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:07:28

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:07:47

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:08:10

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:08:29

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:08:48

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:09:11

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:09:31

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:09:51

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:10:14

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:10:33







20MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:10:53

FCC Part 27&IC RSS 139


B4, Normal
1RB was the worst case




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




5MHz_High_QPSK_1@0(30MHz~18.55GHz)




10MHz_Low_QPSK_1@0(30MHz~18.55GHz)









10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



10MHz_High_QPSK_1@0(30MHz~18.55GHz)






FCC Part 27&IC RSS 199

B7, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:02:03

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:02:25

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:02:47

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:03:11

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:03:33

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:03:56

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:04:21

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:04:43

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:05:06

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:05:30

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:05:53

20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:06:15

FCC Part 27&IC RSS 130

B12, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:34:19

1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:34:37

1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:34:55

3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:35:14

3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:35:32

3MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:35:50

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:36:10

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:36:27

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:36:44

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 26.JAN.2025 10:26:34

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 26.JAN.2025 10:26:49

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 26.JAN.2025 10:27:04

FCC Part 27&IC RSS 130

B17, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:57:17

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:57:36

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:57:56

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:59:14

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:59:34

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:59:54

FCC Part 27&IC RSS 199

B38, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:13:36

5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:13:57

5MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:14:19

10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:14:42

10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:15:03

10MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:15:23

15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:15:47

15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:16:09

15MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:16:31

20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:17:22

20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:17:43

20MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 09:18:07

FCC Part 27&IC RSS 139

B66, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 13:50:46

1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 13:51:06

1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 13:51:27

3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:54:43

3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:55:02

3MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:55:21

5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:55:42

5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:56:01

5MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:56:20

10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:56:40

10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:56:59

10MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:57:18

15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:57:40

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:57:59

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:58:19

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:58:42

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:59:02

20MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 14:59:21

FCC Part 27&IC RSS 199

B41, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 20.FEB.2025 09:55:18

5MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 20.FEB.2025 09:55:39

5MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 20.FEB.2025 09:55:59

10MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 20.FEB.2025 09:56:20

10MHz_Middle_QPSK_1@0(30MHz~27.55GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 20.FEB.2025 09:56:40

10MHz_High_QPSK_1@0(30MHz~27.55GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 20.FEB.2025 09:57:01

