
















ANT L_802.11ax_HE20_26T_Low_UNII 1






ANT L_802.11ax_HE20_26T_Low_UNII 2A






ANT L_802.11ax_HE20_26T_Low_UNII 2C







ANT L_802.11ax_HE20_26T_Low_UNII 3






ANT R_802.11ax_HE20_26T_Low_UNII 1






ANT R_802.11ax_HE20_26T_Low_UNII 2A






ANT R_802.11ax_HE20_26T_Low_UNII 2C







ANT R_802.11ax_HE20_26T_Low_UNII 3






ANT L_802.11ax_HE20_26T_Mid_UNII 1






ANT L_802.11ax_HE20_26T_Mid_UNII 2A






ANT L_802.11ax_HE20_26T_Mid_UNII 2C







ANT L_802.11ax_HE20_26T_Mid_UNII 3






ANT R_802.11ax_HE20_26T_Mid_UNII 1






ANT R_802.11ax_HE20_26T_Mid_UNII 2A






ANT R_802.11ax_HE20_26T_Mid_UNII 2C







ANT R_802.11ax_HE20_26T_Mid_UNII 3






ANT L_802.11ax_HE20_26T_High_UNII 1






ANT L_802.11ax_HE20_26T_High_UNII 2A






ANT L_802.11ax_HE20_26T_High_UNII 2C







ANT L_802.11ax_HE20_26T_High_UNII 3






ANT R_802.11ax_HE20_26T_High_UNII 1






ANT R_802.11ax_HE20_26T_High_UNII 2A






ANT R_802.11ax_HE20_26T_High_UNII 2C







ANT R_802.11ax_HE20_26T_High_UNII 3






ANT L_802.11ax_HE20_242T_UNII 1






ANT L_802.11ax_HE20_242T_UNII 2A






ANT L_802.11ax_HE20_242T_UNII 2C







ANT L_802.11ax_HE20_242T_UNII 3






ANT R_802.11ax_HE20_242T_UNII 1





ANT R_802.11ax_HE20_242T_UNII 2A





ANT R_802.11ax_HE20_242T_UNII 2C







ANT R_802.11ax_HE20_242T_UNII 3



ANT L_802.11n_HT40_UNII 1





ANT L_802.11n_HT40_UNII 2A





ANT L_802.11n_HT40_UNII 2C





Report No.:
CTK-2023-01326
Page (70) / (539) Pages







ANT L_802.11n_HT40_UNII 3



ANT R_802.11n_HT40_UNII 1



ANT R_802.11n_HT40_UNII 2A





ANT R_802.11n_HT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (72) / (539) Pages







ANT R_802.11n_HT40_UNII 3



ANT L_802.11ac_VHT40_UNII 1



ANT L_802.11ac_VHT40_UNII 2A





ANT L_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (74) / (539) Pages







ANT L_802.11ac_VHT40_UNII 3



ANT R_802.11ac_VHT40_UNII 1



ANT R_802.11ac_VHT40_UNII 2A





ANT R_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (76) / (539) Pages







ANT R_802.11ac_VHT40_UNII 3



ANT L_802.11ax_HE40_26T_Low_UNII 1



ANT L_802.11ax_HE40_26T_Low_UNII 2A





ANT L_802.11ax_HE40_26T_Low_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (78) / (539) Pages







ANT L_802.11ax_HE40_26T_Low_UNII 3



ANT R_802.11ax_HE40_26T_Low_UNII 1



ANT R_802.11ax_HE40_26T_Low_UNII 2A





ANT R_802.11ax_HE40_26T_Low_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-01326
Page (80) / (539) Pages



ANT R_802.11ax_HE40_26T_Low_UNII 3