



Industrial Technology Research Institute

Electronics Research & Service Organization

Bldg. 17, 195-4 Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, 310
Taiwan, Republic Of China

TEL : 886-3-5917069 FAX : 886-3-5825720


FCC ID : N89-SAR-1201

Report No. : 500-8707-030

Page 21 of 22

3.7 PHOTOS OF OPEN SITE

(2) For BNC mode






Industrial Technology Research Institute
Electronics Research & Service Organization
Bldg. 17, 195-4 Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, 310
Taiwan, Republic Of China
TEL : 886-3-5917069 FAX : 886-3-5825720

FCC ID : N89-SAR-1201
Report No. : 500-8707-030
Page 22 of 22

3.7 PHOTOS OF OPEN SITE


(2) For BNC mode





3.7 PHOTOS OF OPEN SITE

(1) For RJ-45 mode





Industrial Technology Research Institute

Electronics Research & Service Organization

Bldg. 17, 195-4 Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, 310

Taiwan, Republic Of China

TEL : 886-3-5917069 FAX : 886-3-5825720


FCC ID : N89-SAR-1201

Report No. : 500-8707-030

Page 20 of 22

3.7 PHOTOS OF OPEN SITE

(1) For RJ-45 mode





Industrial Technology Research Institute

Electronics Research & Service Organization
Bldg. 17, 195-4 Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, 310
Taiwan, Republic Of China
TEL : 886-3-5917069 FAX : 886-3-5825720


FCC ID : N89-SAR-1201

Report No. : 500-8707-030

Page 14 of 22

2.7 PHOTOS OF CONDUCTION TEST

(2) For BNC mode





Industrial Technology Research Institute

Electronics Research & Service Organization

Bldg. 17, 195-4 Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, 310
Taiwan, Republic Of China
TEL : 886-3-5917069 FAX : 886-3-5825720

FCC ID : N89-SAR-1201

Report No. : 500-8707-030

Page 13 of 22

2.7 PHOTOS OF CONDUCTION TEST

(1) For RJ-45 mode

