

INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16030912HKG-001(FCC)
16030912HKG-002 (IC)

Equipment Photographs

Model : 91764

(Internal)

