



Report




-6dB Bandwidth NVNT ac40 5815MHz Ant2




-6dB Bandwidth NVNT ac80 5775MHz Ant1

Report




-6dB Bandwidth NVNT ac80 5775MHz Ant2




-6dB Bandwidth NVNT ac80 5785MHz Ant1

Report




-6dB Bandwidth NVNT ac80 5785MHz Ant2




-6dB Bandwidth NVNT ac80 5795MHz Ant1

Report




-6dB Bandwidth NVNT ac80 5795MHz Ant2




-6dB Bandwidth NVNT n20 5745MHz Ant1

Report




-6dB Bandwidth NVNT n20 5745MHz Ant2




-6dB Bandwidth NVNT n20 5785MHz Ant1

Report




-6dB Bandwidth NVNT n20 5785MHz Ant2




-6dB Bandwidth NVNT n20 5825MHz Ant1

Report




-6dB Bandwidth NVNT n20 5825MHz Ant2




-6dB Bandwidth NVNT n40 5755MHz Ant1

Report




-6dB Bandwidth NVNT n40 5755MHz Ant2




-6dB Bandwidth NVNT n40 5785MHz Ant1

Report




-6dB Bandwidth NVNT n40 5785MHz Ant2



-6dB Bandwidth NVNT n40 5815MHz Ant1

Report



-6dB Bandwidth NVNT n40 5815MHz Ant2

