



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2001288
Quote Number: QRTL01-324
Dates of Tests: November 10, 2001
FCC Part 90 Certification &
Industry Canada RSS-119

Exhibit 12

APPENDIX K: TEST PHOTOGRAPHS



PHOTOGRAPH 2: RADIATED EMISSIONS FRONT VIEW



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2001288
Quote Number: QRTL01-324
Dates of Tests: November 10, 2001
FCC Part 90 Certification &
Industry Canada RSS-119

Exhibit 12



PHOTOGRAPH 3: RADIATED EMISSIONS REAR VIEW



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2001288
Quote Number: QRTL01-324
Dates of Tests: November 10, 2001
FCC Part 90 Certification &
Industry Canada RSS-119

Exhibit 12



PHOTOGRAPH 4: SUBSTITUTION DIPOLE ANTENNA USED FOR FREQUENCIES (30 MHZ – 1 GHZ)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Work Order: 2001288
Quote Number: QRTL01-324
Dates of Tests: November 10, 2001
FCC Part 90 Certification &
Industry Canada RSS-119

Exhibit 12



PHOTOGRAPH 5: SUBSTITUTION HORN ANTENNA USED FOR FREQUENCIES (1 GHZ-18 GHZ)