











ANT R_802.11ax_HE40_106T_Mid_UNII 1



ANT R_802.11ax_HE40_106T_Mid_UNII 2A





ANT R_802.11ax_HE40_106T_Mid_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (301) / (539) Pages







ANT R_802.11ax_HE40_106T_Mid_UNII 3



ANT L_802.11ax_HE40_106T_High_UNII 1



ANT L_802.11ax_HE40_106T_High_UNII 2A





ANT L_802.11ax_HE40_106T_High_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (303) / (539) Pages







ANT L_802.11ax_HE40_106T_High_UNII 3



ANT R_802.11ax_HE40_106T_High_UNII 1



ANT R_802.11ax_HE40_106T_High_UNII 2A





ANT R_802.11ax_HE40_106T_High_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (305) / (539) Pages







ANT_R_802.11ax_HE40_106T_High_UNII 3



ANT L_802.11ax_HE40_242T_Low_UNII 1



ANT L_802.11ax_HE40_242T_Low_UNII 2A





ANT L_802.11ax_HE40_242T_Low_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (307) / (539) Pages







ANT L_802.11ax_HE40_242T_Low_UNII 3



ANT R_802.11ax_HE40_242T_Low_UNII 1



ANT R_802.11ax_HE40_242T_Low_UNII 2A





ANT R_802.11ax_HE40_242T_Low_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (309) / (539) Pages







ANT R_802.11ax_HE40_242T_Low_UNII 3



ANT L_802.11ax_HE40_242T_High_UNII 1



ANT L_802.11ax_HE40_242T_High_UNII 2A





ANT L_802.11ax_HE40_242T_High_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (311) / (539) Pages







ANT L_802.11ax_HE40_242T_High_UNII 3



ANT R_802.11ax_HE40_242T_High_UNII 1



ANT R_802.11ax_HE40_242T_High_UNII 2A





ANT R_802.11ax_HE40_242T_High_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (313) / (539) Pages







ANT_R_802.11ax_HE40_242T_High_UNII 3



ANT L_802.11ax_HE40_484T_UNII 1



ANT L_802.11ax_HE40_484T_UNII 2A





ANT L_802.11ax_HE40_484T_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-01326
Page (315) / (539) Pages







ANT L_802.11ax_HE40_484T_UNII 3



ANT R_802.11ax_HE40_484T_UNII 1



ANT R_802.11ax_HE40_484T_UNII 2A





ANT R_802.11ax_HE40_484T_UNII 2C




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2023-01326
Page (317) / (539) Pages






ANT R_802.11ax_HE40_484T_UNII 3




ANT L_802.11ac_VHT80_UNII 1




ANT L_802.11ac_VHT80_UNII 2A




ANT L_802.11ac_VHT80_UNII 2C






ANT L_802.11ac_VHT80_UNII 3




ANT R_802.11ac_VHT80_UNII 1




ANT R_802.11ac_VHT80_UNII 2A




ANT R_802.11ac_VHT80_UNII 2C





ANT R_802.11ac_VHT80_UNII 3



ANT L_802.11ax_HE80_26T_Low_UNII 1




ANT L_802.11ax_HE80_26T_Low_UNII 2A




ANT L_802.11ax_HE80_26T_Low_UNII 2C





ANT L_802.11ax_HE80_26T_Low_UNII 3



ANT R_802.11ax_HE80_26T_Low_UNII 1




ANT R_802.11ax_HE80_26T_Low_UNII 2A




ANT R_802.11ax_HE80_26T_Low_UNII 2C






ANT R_802.11ax_HE80_26T_Low_UNII 3




ANT L_802.11ax_HE80_26T_Mid_UNII 1




ANT L_802.11ax_HE80_26T_Mid_UNII 2A




ANT L_802.11ax_HE80_26T_Mid_UNII 2C





ANT L_802.11ax_HE80_26T_Mid_UNII 3




ANT R_802.11ax_HE80_26T_Mid_UNII 1




ANT R_802.11ax_HE80_26T_Mid_UNII 2A




ANT R_802.11ax_HE80_26T_Mid_UNII 2C





ANT R_802.11ax_HE80_26T_Mid_UNII 3




ANT L_802.11ax_HE80_26T_High_UNII 1




ANT L_802.11ax_HE80_26T_High_UNII 2A




ANT L_802.11ax_HE80_26T_High_UNII 2C





ANT L_802.11ax_HE80_26T_High_UNII 3




ANT R_802.11ax_HE80_26T_High_UNII 1




ANT R_802.11ax_HE80_26T_High_UNII 2A




ANT R_802.11ax_HE80_26T_High_UNII 2C





ANT R_802.11ax_HE80_26T_High_UNII 3




ANT L_802.11ax_HE80_52T_Low_UNII 1




ANT L_802.11ax_HE80_52T_Low_UNII 2A



ANT L_802.11ax_HE80_52T_Low_UNII 2C





ANT L_802.11ax_HE80_52T_Low_UNII 3



ANT R_802.11ax_HE80_52T_Low_UNII 1



ANT R_802.11ax_HE80_52T_Low_UNII 2A



ANT R_802.11ax_HE80_52T_Low_UNII 2C



ANT R_802.11ax_HE80_52T_Low_UNII 3