



B17 , Normal
1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




5MHz_Low_QPSK_25@0(30MHz~8.16GHz)




5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




5MHz_Middle_QPSK_25@0(30MHz~8.16GHz)




5MHz_High_QPSK_1@0(30MHz~8.16GHz)



5MHz_High_QPSK_25@0(30MHz~8.16GHz)




10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo: RSHA240322001 Tester:Jason Lu
Date: 29 NOV 2024 21:49:51

10MHz_Low_QPSK_50@0(30MHz~8.16GHz)




ProjectNo: RSHA240322001 Tester:Jason Lu
Date: 29 NOV 2024 21:50:09

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo: RSHA240322001 Tester:Jason Lu
Date: 29 NOV 2024 21:50:28

10MHz_Middle_QPSK_50@0(30MHz~8.16GHz)




ProjectNo: RSHA240322001 Tester:Jason Lu
Date: 29 NOV 2024 21:50:47

10MHz_High_QPSK_1@0(30MHz~8.16GHz)



ProjectNo: RSHA240322001 Tester:Jason Lu
Date: 29 NOV 2024 21:51:06

10MHz_High_QPSK_50@0(30MHz~8.16GHz)



ProjectNo: RSHA240322001 Tester:Jason Lu
Date: 29 NOV 2024 21:51:25