



SRAM  
1000 West Fulton Market, 4th Fl.  
Chicago, IL 60607 USA

tel: +1 (312) 664-8800  
fax: +1 (312) 664-8826

### **Product Equality Declaration**

SRAM LLC declares for the following products:

Left Shifter		Right Shifter	
<b>Model</b>	00020	<b>Model</b>	00120
<b>FCC ID</b>	C9O-LSBB2	<b>FCC ID</b>	C9O-RSBB2

The only differences between the two devices (Left Shifter 00020) and Right Shifter (00120):

**1. F/W:**

the firmware is identical except for:

- pin assignment due to mirror image of left and right PCBAs
- identifier in COM after the components are paired into a system

**2. H/W:**

Looking at the schematic, left and right PCBAs look identical except for

- due to mirror image of left and right PCBAs, the microcontroller has different pin assignments
- due to different pin assignment of the micro, some of the trace layouts may vary, but due to the PCBAs being so small, the different is in millimeters or less

Best Regards,

---

Leo Yermakov  
Regulatory Compliance Manager  
March 25, 2020