



Intertek Testing Services ETL SEMKO

Report No.: 00038381

Tested By: Hong, Report No.: 00038381

Scan Settings (1 Range)


----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 00038381

Tested By:Hong, Report No.:00038381

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl No.: N/A