

Tranzeo EMC Labs Inc.
#2 - 11720 Stewart Crescent
Maple Ridge, BC
Canada V2X 9E7

TR-AP5A-N Test Report
Appendix A – Internal Photos

CONFIDENTIAL

14 January 2005

Report Number: TRL140105.1



Bruce Balston, EMC Lab Manager



Andrew Marles, Technical Writer

A.1 Internal Photos



Figure 1 – Carrier card



Figure 2 – Carrier card reverse



Figure 3 – Radio card



Figure 4 – Radio card without rf shield



Figure 5 – Radio card reverse



Figure 6 – Carrier Card and Radio



Figure 7 – Backplate reverse (ext of unit)




Figure 8 – Carrier/radio mounted to backplate



Figure 9 – Structure plate installed




Figure 10 – EMI Tape installed



Figure 11 – TR-AP5A-N front cover installed