

YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD.
No.666 Hu'an Rd. Huli District Xiamen City, Fujian, P.R. China
Tel: 86-592-5702000
Fax: 86-592-5702455
Email: chenjl@yealink.com

Date: 2022-11-22

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road


Columbia, MD 21046

Dear Sir/Madam,

The Main chip, model: ATS2831P, installed in our product Bluetooth USB Dongle, model: BT51A, BT52A, FCC ID: T2C-BT51, supports BDR (GFSK), EDR ($\pi/4$ -DQPSK, 8DPSK), BLE 1M and BLE 2M functions. For use in America and this chip will not support/enable BLE 1M and BLE 2M. The BLE 1M and BLE 2M function has been shielded by the manufacturer using the software.

Sincerely Yours,

Signature:



Stone Lu

Vice General Manager