



*Andrew Corporation
108 Rand Park Drive
Garner, NC U.S.A. 27529
Tel: (919) 771-2570
Fax: (919) 771-2360
www.andrew.com*

25 July 2006

A request has been made for the FCC identifier of the master hardware for the TFAM80/92/19E product. In the past, dating back to 1998, this has not been required. The remote unit, TFAM80/92/19E, has been the only unit requiring an FCC identifier. The remote unit is the only part of the hardware that radiates an RF signal.

Regards,

Michael Williamson