



3390 East Harmony Road  
Fort Collins  
Colorado 80528  
United States

Date: April 19, 2021

Federal Communications Commission  
Office of Engineering and Technology Laboratory Division  
7435 Oakland Mills Rd  
Columbia MD 21046-1609

To whom it may concern,

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by HP Inc. will establish a new FCC ID: B94-RTL8821CES under HP Inc. grantee code for purpose of marketing. The original grant to Realtek Semiconductor Corp. will remain in effect.

Per 2.933(b)

1. The original identification is TX2-RTL8821CE.
2. The original grant date is **12/12/2016**
3. The equipment is electrically identical. Only the trade name and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.

The following files are electronically submitted as attachments:

- ♦ Cover Letter
- ♦ FCC ID label format and location

Sincerely yours,

A handwritten signature in black ink that reads 'Liang Rong Chiao'.

---

Liang Rong Chiao

Worldwide Technical Regulations

HP Inc.

10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan

frances.liang@hp.com

T +886-2-37892469