

RTS

Research In Motion Limited
295 Phillip Street
Waterloo, Ontario
Canada N2L 3W8
+1 519 888 7465, fax +1 519 888 6906
E-mail: info@rim.com

August 22, 2005

Attention: Bruno Clavier

TIMCO ENGINEERING INC.
849 NW State Road 45
Newberry, Florida 32669

Subject: Response to the TIMCO Correspondence Reference Number 1683UC5 for clarification on RIM BlackBerry Wireless Handheld FCC ID L6ARAW20IN.

Dear Bruno:

The following addresses your inquiry Correspondence Reference Number 1683UC5:

1. Please see the measured results in the updated report RTS-0184-0508-01 Rev1 & RTS-0184-0508-01-ic, page 12.
2. Bluetooth application is with headset for hands free operation only. Therefore, no head SAR testing with BT on is applicable. Worst case body SAR with holster was tested with BT turned on and SAR value was determined to be lower.
3. Please see attached file, Internal photos_2.
4. Please see attached file, Internal photos_2.

Yours truly,



Masud S. Attayi, P.Eng.,
Senior Compliance Engineer,
RIM Testing Services (RTS)
Tel: +1 519 888-7465 x2442
Fax: +1 519 888-6906
Email: mattayi@rim.com