

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN

## INTERNAL PHOTOGRAPHS




Photo 1- Back of EUT with Back Cover Removed

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN

---



**Photo 2- Right Side of EUT with Back Cover Removed**

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN

---



**Photo 3- Top of EUT with Back Cover Removed**

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN



**Photo 4- Left Side of EUT with Back Cover Removed**

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN

---




**Photo 5- Bottom of EUT with Back Cover Removed**



US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:


FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN



**Photo 6- Front Side of Circuit Board #1**

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:


FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN



**Photo 9- Back Side of Circuit Board #1 with Circuit Board #2 Attached**

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN



**Photo 8- Back Side of Circuit Board #1 with Circuit Board #2 Removed**



US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN




Photo 9- Front Side of Circuit Board #2

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN




Photo 10- Back Side of Circuit Board #2

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN




**Photo 11- Back Side of EUT with Circuit Board #1 Removed**



US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN

---



**Photo 12- Bottom of EUT with Circuit Board #1 Removed**



US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN



**Photo 13- Left Side of EUT with Circuit Board #1 Rmved**

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN



**Photo 14- Top of EUT with Circuit Board #1 Removed**

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN



**Photo 15- Right Side of EUT with Circuit Board #1 Removed**

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN




Photo 16- Top of Circuit Board #3, with Radio



US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN




Photo 17- Back of Circuit Board #3

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN





Photo 17- Radio on Circuit Board #3

US Tech Test Report:  
Report Number:  
Customer:  
FCC ID:  
IC:  
Issue Date:  
Model:

FCC Part 15.249/RSS 210  
14-0201  
Acuity Brands Lighting  
2ADCB-FCS7TSN  
6715C-FCS7TSN  
September 3, 2014  
FCS 7TSN



**Photo 18- Back of EUT with all PCBs Removed**