




Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A4305
Test: 211229
Test to: CFR47 15C, RSS-247
File: A04272 Short Term Conf TSup


SN's: 1095389233, 1961091609
FCC ID: IPH-A4305
IC: 1792A-A4305
Date: March 10, 2022
Page 1 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A4305
Test: 211229
Test to: CFR47 15C, RSS-247
File: A04272 Short Term Conf TSup


SN's: 1095389233, 1961091609
FCC ID: IPH-A4305
IC: 1792A-A4305
Date: March 10, 2022
Page 2 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A4305
Test: 211229
Test to: CFR47 15C, RSS-247
File: A04272 Short Term Conf TSup

SN's: 1095389233, 1961091609
FCC ID: IPH-A4305
IC: 1792A-A4305
Date: March 10, 2022
Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A4305
Test: 211229
Test to: CFR47 15C, RSS-247
File: A04272 Short Term Conf TSup

SN's: 1095389233, 1961091609
FCC ID: IPH-A4305
IC: 1792A-A4305
Date: March 10, 2022
Page 4 of 4