


INTERTEK TESTING SERVICE

Report No.: 17020163HKG-002

Equipment Photographs

Model : FNF59

(Internal)



FCC ID: PIYFNF59-17A5H


INTERTEK TESTING SERVICE

Report No.: 17020163HKG-002

Equipment Photographs

Model : FNF59

(Internal)



FCC ID: PIYFNF59-17A5H



INTERTEK TESTING SERVICE

Report No.: 17020163HKG-002

Equipment Photographs

Model : FNF59

(Internal)



FCC ID: PIYFNF59-17A5H


INTERTEK TESTING SERVICE

Report No.: 17020163HKG-002

Equipment Photographs

Model : FNF59

(Internal)



FCC ID: PIYFNF59-17A5H



INTERTEK TESTING SERVICE

Report No.: 17020163HKG-002

Equipment Photographs

Model : FNF59

(Internal)



FCC ID: PIYFNF59-17A5H


INTERTEK TESTING SERVICE

Report No.: 17020163HKG-002

Equipment Photographs

Model : FNF59

(Internal)



FCC ID: PIYFNF59-17A5H


INTERTEK TESTING SERVICE

Report No.: 17020163HKG-002

Equipment Photographs

Model : FNF59

(Internal)



FCC ID: PIYFNF59-17A5H



INTERTEK TESTING SERVICE

Report No.: 17020163HKG-002

Equipment Photographs

Model : FNF59

(Internal)



FCC ID: PIYFNF59-17A5H

INTERTEK TESTING SERVICE

Report No.: 17020163HKG-002

Equipment Photographs

Model : FNF59

(Internal)

