

December 29, 2005

RE: Procare International

FCC ID: POSEF6216

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) The FCC ID on the Labeling is incorrect. Please review. If you have difficulties with the proper label format, we will be happy to assist.
- 2.) This device transmits analog FM music to a common FM broadcast receiver. Therefore, both the amplitude of the audio and the frequency of the applied audio will directly affect the bandwidth of the signal. I am not satisfied that this device has shown compliance with the 200KHz bandwidth requirements of 15.239(a). Please provide details on the modulation used during testing to 15.239(a)

Willing

William H. Graff President and Director of Engineering

mailto: whgraff@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.