Thundercomm Technology Co., Ltd

ADD: 4F, Taixiang Building, 1A Longxiang Rd Haidian Dist, Beijing, China,100191

Tel: +86 010-82036511 Fax: +86 010-82036511

Email: Zhouqy0710@thundersoft.com

Date: 2019-02-28

## FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

Subject: FCC Class II Permission change for FCC ID: 2AOHHTURBOXSOMD820 Original Grant Date:2018/9/19

Dear Sir/Madam,

This is to request a Class II permission change to our Thundersoft TurboX-D820-SoM, Model TurboX-D820, TurboX (FCC ID: 2AOHHTURBOXSOMD820), the device is identical to the previously certified except for the changes as below for details;

- 1) Original have two PCB antennas, the antenna gain is 5dbi. The new application is the addition of new FPC antenna, antenna gain is 2dbi.
- 2) Change some capacitance in the main board, the change don't effect RF characteristic.

This authorization is valid until further written notice from the applicant.

Please contact me if you have any questions or need future information regarding this application.

Sincerely Yours, Signature:

aiyong Zhou

Qiyong Zhou Manager