

**October 6,2000**

**Federal Communications Commission  
Equipment Authorization Division,  
Applications Processing Branch  
7435 Oakland Mills Road  
Columbia, MD 21046**

**RE) FCC ID: BRWXF631 (EA98953)**

**To whom it may concern;**

**Please refer to the additional information listed below while reviewing the BRWXF631 System.**

- 1) Section 95.645 (b) states that plug-in crystals must not be accessible to the user. Indicate whether or not crystals are accessible to the user.**

Although the transmitter crystal is visible from the back of the transmitter, each crystal is glued in place prior to shipment making it a permanent installation. Consumer removal of the crystal will normally result in damage to the crystal. Therefore, frequency changes are done at the service center only.

- 2) The Manual must contain warnings per section 95.653**

A) Please refer to the manual attachment for this information

B) All content for operation is contained in the instruction manual.

- 1) All instructions are contained in the instruction manual.
- 2) There are no adjustments accessible to the user that would be in violation with the FCC rules, except as noted in the section #3 below.
- 3) Noted. We will be adding the following information to the instruction manual under "Frequency Chart":

"Note: The Federal Communications Commission (FCC) requires that changes in radio frequency must be performed by an authorized service technician only (Horizon Service Center).

Any frequency changes made by a non-certified technician may result in a violation of the FCC rules"

- 4) This section is not applicable to our use.

**If there is any further information required, please contact me directly at:**

**Horizon Hobby Distributors**  
**ATTN: Len Sabato**  
**Fax: 217-355-0058**  
**Phone: 217-352-1958 Ext. 454**  
[lsabato@horizonhobby.com](mailto:lsabato@horizonhobby.com)

Best Regards;  
Len Sabato