

3390 East Harmony Road
Fort Collins
Colorado 80528
United States



FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

To whom it may concern:

This device with FCC ID: **B94HNI61PAR** integrates a WWAN module:

	FCC ID	Grant Date
CAT-M Module	2BF7TTX520GL	08/30/2024

No hardware design changes are made on the modules, and the software has not been changed to increase the RF output power of the modules. Pursuant to KDB 996369 D02v01, the original modular report as following are submitted to represent the compliance of Part 22/24/27/90/96 conducted RF testing items of this device.

Report Number
SZCR240600235202

The radiated RF testing items are tested on this host device, and the test report is submitted additionally.

Sincerely,

A handwritten signature in black ink that reads 'Liang Rong Chiao'.

Liang Rong Chiao

Worldwide Technical Regulations
HP International Pte. Ltd., Taiwan Branch
10F-1, No. 66, Jingmao 2nd Road, Nangang District, Taipei 11568. Taiwan
frances.liang@hp.com
T +886-2-37892469