



# Intertek Testing Services

## ETL SEMKO

Sep. 17, 2002

Subject: Permissive Class II change for FCC ID: M4Y-03251

Dear Sir,

The Wireless PC Card, Model No.: XI-325, FCC ID: M4Y-03251 need to do the Class II change due to the changing of the antennas. We evaluated that the changed would NOT affect the RF characteristics except for the Radiated Spurious Emission and Band-edge.

The product has conducted the Radiated Spurious Emission test and Band-edge test compliance with the CFR 47 Part 15 Subpart C 15.247 and relative regulations. For more details, please refer to the test report.

If you have any question, please feel free to contact me.

Best Regards,

A handwritten signature in black ink, appearing to read 'Elton Chen'.

**Elton Chen**

**Supervisor**

**Intertek Testing Service Taiwan Ltd.**