

Report number: 2002180 FCC: Part 15.247 Industry Canada: RSS-210 FCC ID: GU67410-02 M/N: 7410-02


APPENDIX M: INTERNAL PHOTOGRAPHS




PHOTOGRAPH 9: MAIN PRINTER CONTROL BOARD REMOVED, DC POWER SUPPLY PCB VISIBLE, CABLE TO RIGHT ANGLE ANTENNA




PHOTOGRAPH 10: MOUNTED MAIN PCB WITH PRINT SERVER CONNECTOR




PHOTOGRAPH 11: PRINT SERVER AND KEYPAD REMOVED




PHOTOGRAPH 12: PRINT SERVER PLUGGED INTO MOUNTED MAIN PCB WITH CABLE TO RIGHT ANGLE ANTENNA




PHOTOGRAPH 13: PRINT SERVER AND WLAN CARD MOUNTED IN PLACE WITH CABLE TO RIGHT ANGLE ANTENNA



PHOTOGRAPH 14: MAIN PRINTER SYSTEM CONTROL BOARD WITH CONNECTOR WHERE PRINT SERVER PLUGS IN




PHOTOGRAPH 15: MAIN PRINTER SYSTEM CONTROL BOARD BACK VIEW



PHOTOGRAPH 16: PRINT SERVER TOP VIEW



PHOTOGRAPH 17: PRINT SERVER REAR VIEW



PHOTOGRAPH 18: PRINT SERVER MOUNTING ADAPTER PCB