

YOU WROTE:

7) Since this may be mounted on ceiling or walls, all 3 axis should have been checked. Has the device been checked in all 3 axis to ensure worse case results are obtained. Note the fundamental seems to have < 1 dB margin to the limit.

I REPLY:

I verified with our OATS technician, Chris Locke, that all three axis orientations were checked.