

Internal Photographs

For

XX6STP9280

Contents

XX6STP9280 WITH HEATSINK.....	3
XX6STP9280 WITHOUT HEATSINK.....	4
XX6STP9280 WITHOUT CANS.....	5
XX6STP9280 LCD SIDE.....	6
XX6STP9280 LCD SIDE LESS FRAME.....	7
XX6STP9280 LCD SIDE LESS CANS.....	8

Sepura plc

Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9280 With Heatsink



Sepura plc

Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9280 Without Heatsink



Sepura plc


Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9280 Without Cans



Sepura plc


Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9280 LCD Side



Sepura plc


Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9280 LCD side less frame



Sepura plc

Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9280 LCD side without cans

