

EMC Technologies Report Number: M050215_Cert_WLL4070_11abg_NII_BT

APPENDIX K
Harmonics - WLL4070 802.11a (NII)



Harmonics – Channel 36

Marker 1 [T1]

RBW 100 kHz RF Att 30 dB

Ref Lvl

-1.48 dBm

VBW 300 kHz

17.5 dBm


5.14228457 GHz

SWT

9.8 s

Unit

dBm



Date: 17.FEB.2005 09:05:38



Harmonics - Channel 52

Marker 1 [T1]

RBW 100 kHz RF Att 30 dB

Ref Lvl

2.45 dBm

VBW 300 kHz

17.5 dBm


5.22044088 GHz

SWT

9.8 s

Unit

dBm



Date: 17.FEB.2005 09:02:11



Harmonics - Channel 64

Marker 1 [T1]

RBW 100 kHz RF Att 30 dB

Ref Lvl 1.23 dBm


VBW 300 kHz

17.5 dBm

5.29859719 GHz

SWT 9.8 s Unit

dBm



Date: 17.FEB.2005 08:58:15



Harmonics - Channel 42 Turbo

Marker 1 [T1]

RBW 100 kHz RF Att 30 dB

Ref Lvl

-0.57 dBm

VBW 300 kHz

17.5 dBm


5.14228457 GHz

SWT

9.8 s

Unit

dBm



Date: 17.FEB.2005 08:49:41



Harmonics - Channel 50 Turbo

Marker 1 [T1]

RBW 100 kHz RF Att 30 dB

Ref Lvl

2.03 dBm


VBW 300 kHz

17.5 dBm

5.22044088 GHz

SWT 9.8 s Unit

dBm



Date: 17.FEB.2005 08:52:08



Harmonics - Channel 58 Turbo

Marker 1 [T1]

RBW 100 kHz RF Att 30 dB

Ref Lvl

1.10 dBm

VBW 300 kHz


17.5 dBm

5.29859719 GHz

SWT 9.8 s

Unit

dBm



Date: 17.FEB.2005 08:55:09

