

Test & Certification Center (TCC) - Dallas

FCC ID: GMLRH-42

Test Report #: 03-RF-0142.001

August 28, 2003

Ver 1.0

4. EQUIPMENT-UNDER-TEST (EUT)

The results in this report relate only to the items listed below:

4.1 Description of Tested Device(s):

Test Performed	Mode of Operation	Date of Receipt	Condition of Sample	Item	Identifying Information
2.1053, 22.913(a), 24.232(b)(c)	AMPS/TDMA 800	23-June-2003	Good	Phone	FCC ID: GMLRH-42 Type: RH-42 HW: 1172f SW: 3.02 ESN: 25516777215* HW: 1173f SW: 3.02 ESN: 25516777215* *Dummy ESN
2.1049(c)(1), 2.1051, 2.1055(d)(1)(2), 2.1055(a)(1)(b), 22.917, 24.235, 24.238(a)(b)	N/A	N/A	N/A	N/A	Not Tested
2.1049(c)(1), 2.1051, 2.1053, 2.1055(d)(1)(2), 2.1055(a)(1)(b), 22.913(a), 22.917, 24.232(b)(c), 24.235, 24.238(a)(b)	N/A	N/A	N/A	N/A	Not Tested

4.2 Photograph of Tested Device(s):

Refer to attached EXHIBITS