



**Intermec**

**Intermec  
Technologies  
Corporation**

6001 36<sup>th</sup> Avenue West  
Everett, Washington 98203  
United States  
**tel** 425.348.2600  
**fax** 425.355.9551  
[www.intermec.com](http://www.intermec.com)

19-NOV-2004

Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, Maryland 21046


**RE: Tune-up Procedure for FCC ID: EHASMC46 GSM Module in 700C Hand Held Computer**

To whom it may concern,

The MC46 tri-band GSM module requires no adjustments of components after assembly. The 700C hand held computer host device, likewise, requires no adjustments of components after assembly. Settings for radio and hand held computer operation require specialized equipment only available to Intermec manufacturing and service personnel.

Please Contact me if there are any questions.

Yours truly,



Scott J. Holub  
Regulatory Compliance Engineer III  
Intermec Technologies Corporation  
550 Second Street S.E.  
Cedar Rapids, IA 52401 USA