

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission **(Mode 1 to 3)**




Photo 1




Photo 2

Radiated Spurious Emission
(Mode 4 to 11)



Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


Worst Case Position

(Mode 1 to 3)
Below 30 MHz: X-axis
Above 30 MHz: X-axis

X-axis



Y-axis



Z-axis



(Mode 4 to 11)
Below 30 MHz: Z-axis
Above 30 MHz: X-axis

X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.
Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN
Telephone : +81 596 24 8999
Facsimile : +81 596 24 8124