

EMC Technologies Report Number: M060223_Cert_AR5BXB6_NII


APPENDIX K

HARMONICS



Harmonics – Channel 36

Marker 1 [T1]	REBW	300 kHz	RF Att	30 dB
Ref Lvl		6.95 dBm	VBW	1 MHz
15 dBm		5.14228457 GHz	SWT	1.1 s
			Unit	dBm




Date: 20.FEB.2006 11:58:25



Harmonics - Channel 52

	Marker 1 [T1]	RBW	300 kHz	RF Att	30 dB
Ref Lvl	7.08 dBm	VBW	1 MHz		
15 dBm	5.22044088 GHz	SWT	1.1 s	Unit	dBm




Date: 20.FEB.2006 12:00:45




Harmonics - Channel 64

Marker 1 [T1]	RBW	300 kHz	RF Att	30 dB
Ref Lvl	6.89 dBm	VBW	1 MHz	
15 dBm	5.29859719 GHz	SWT	1.1 s	Unit dBm




Date: 20.FEB.2006 12:02:51



Harmonics - Channel 42 (Turbo)

Harmonics - Channel 50 (Turbo)

Ref Lvl	Marker 1 [T1]	RBW	300 kHz	RF Att	30 dB
15 dBm	6.27 dBm	VBW	1 MHz		
	5.22044088 GHz	SWT	1.1 s	Unit	dBm




Date: 20.FEB.2006 11:51:55



Harmonics - Channel 58 (Turbo)

Marker 1 [T1] RBW 300 kHz RF Att 30 dB
Ref Lvl 6.09 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 1.1 s Unit dBm



Date: 20.FEB.2006 11:49:52

