

Us Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS



Figure 1. Radiated Emissions Measurement Photo (Front View)

Us Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS




Figure 2. Radiated Emissions Measurement Photo, 30 to 200 MHz

Us Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS





Figure 3. Radiated Emissions Measurement Photo, 200 to 1000 MHz

Us Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS



**Figure 4. Radiated Emissions Measurement, above 1000 MHz and
Variation in Operating Frequency**

Us Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS



Figure 5. Input Power Test Configuration

Us Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS



Figure 6. Radiation Leakage w/ RF Probe

Us Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 18 Subpart C
APYDMR0182
23-0051
May 24, 2023
Sharp Corporation
SWB3085HS




Figure 7. Conducted Emissions Measurement Photo