

FF802
Nov.2, 98

Difficulty with placing or receiving calls?
The security code may be lost. Reset by
placing handset on base for 10 seconds. If
phone still doesn't work, consult Owner's
Manual or Quick Reference Guide.



CONTAINS NICKEL-CADMIUM
BATTERY. BATTERY MUST BE
RECYCLED OR DISPOSED OF
PROPERLY.

FOR SERVICE CALL 1-800-366-0937

Call Before Sending Pre-paid to
the Service Center Nearest you:
Southwestern Bell Freedom Phone
150 Milford Road, East Windsor, NJ 08520
or 7475N. Glen Harbor Blvd., Glendale, AZ 85307



Southwestern Bell
Freedom Phone®

MODEL NO.
FF802

CONFORMS TO ANSI/UL STD. 1459

Complies with Part 68 FCC Rules
FCC REG. NO.: 2B3CHN-30039-W4-E
FCC ID: LBBFF802
REN: 1.0B
MADE IN CHINA

USES JACK:
USOC RJ11C



THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE
FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE,
AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING
INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION.
PRIVACY OF COMMUNICATIONS MAY NOT BE ENSURED WHEN USING THIS PHONE.

HAC AT 0998

S/N:CXXXXXX

CAUTION
TO REDUCE RISK OF FIRE, USE
ONLY 9V CARBON ZINC OR
ALKALINE BATTERIES.

FF802
Nov. 2, 98

