TEL: +82 31 333 4093 FAX: +82 31 333 4094

San 21-8 Goan-Ri, Baekam-Myun, Yongin-Si, Kyunggi-Do, KOREA

July 25, 2001

Underwriters Laboratories Inc. 333 Pfingston Road Northbrook, Illinois 60062-2096 U.S.A.

Subject: Statement of Modification FCC ID: C5F7NFCML510B

Gentlemen:

The model L510B1 is exactly the same construction as model L510B (FCC ID: C5F7NFCML510B) except for the followings.

No.	Item	L510B		L510B1		Remark
		Loc.	Part-Desc.	Loc.	Part-Desc.	
1	Model Name	L510B		L510B1		Same FCC ID
2	Panel		L150X1M-2		L150X2M-1	
3	Array Component	RP11,RP12, P13	300 Ohm, Bead			Eliminated Parts
4	Array Component	RP1~RP10	300 Ohm, Bead	RP1~RP10	33 Ohm, Resistor	Changed Spec.
5	DC/AC Inverter		BAI-1503		FLI-1501, HK1512DW	Changed Spec.
6	Main PCB		Size: 154 x 100		Size: 138 x 100	Changed a PCB Pattern

Should you have any questions or comments concerning the above, please contact the undersigned.

Joon H. Lee

Chief of EMC Group

IST Co.,Ltd.