#### INTERNAL PHOTOS

















Note: Productions samples will have the external coaxial connector connected directly to U.fl connector J3. The tested sample had a faulty connector that had to be bypassed for testing. This change did not bypass any components or affect the RF output power delivered to the antenna.

5

J3





#### **WWW.SGS.COM**

