

Dear reviewer,

Due to the change in WLAN antenna (antenna gain increased about 0.5 dBi). We have re-conducted partial of the tests. Please discard following files and used the new files which have “-rev” suffix.

Affected old files list below:

A. For H9PMC7094

1. Int pho_H9PMC7094.pdf
2. Test Rpt (15.247)-1_H9PMC7094.pdf
3. Test Rpt (15.247)-2_H9PMC7094.pdf
4. Test Rpt (15.407)_H9PMC7094.pdf
5. Test Rpt (Part 22)_H9PMC7094.pdf
6. Test Rpt (Part 24)_H9PMC7094.pdf
7. Test Rpt-SAR (Appendix A)-1_H9PMC7094.pdf
8. Test Rpt-SAR (Appendix A)-2_H9PMC7094.pdf
9. Test Rpt-SAR (Appendix A)-3_H9PMC7094.pdf
10. Test Rpt-SAR_H9PMC7094.pdf

B. For H9PMC7090

1. Int pho_H9PMC7090.pdf
2. Test Rpt (15.247)-1_H9PMC7090.pdf
3. Test Rpt (15.247)-2_H9PMC7090.pdf
4. Test Rpt (15.407)_H9PMC7090.pdf
5. Test Rpt-SAR (Appendix A)-1_H9PMC7090.pdf
6. Test Rpt-SAR (Appendix A)-2_H9PMC7090.pdf
7. Test Rpt-SAR_H9PMC7090.pdf

Best regards,

ADT