
# Appendix C. Set up Photograph

## Conducted Emission

Mode 1



FRONT VIEW


REAR VIEW



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C4
Report Issued Date : Dec. 22, 2005
Report Version : Rev. 01


Report No.: FR5N2312





SIDE VIEW


## Mode 2




**FRONT VIEW** 


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C4
Report Issued Date : Dec. 22, 2005
Report Version : Rev. 01





## **REAR VIEW**




## SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C4
Report Issued Date : Dec. 22, 2005
Report Version : Rev. 01



## **Radiation Emission**



**FRONT VIEW** 

**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C4
Report Issued Date : Dec. 22, 2005
Report Version : Rev. 01